

1999–2020 Chevrolet Express Van/GMC Savana Blower Motor Speed Selection Troubleshoot

gpd

Global Parts Distributors, LLC

TECH TIP



#88

gpdtechtips.com


Experiencing an issue with the blower motor speed selection on a 1999–2020 Chevrolet Express Van or GMC Savana?

The most likely problem is the blower motor resistor has failed and will require replacement. Another common problem is the electrical connector/blower motor resistor pigtail connected to the blower motor resistor may have a short causing the socket connection to melt.

Signs of a short can be noticed by melted plastic components.



The 1711755 is a replacement blower motor resistor pigtail that comes with the same color coding as the wiring harness and includes heat shrink over the butt connectors. All you need to do is cut the old pigtail connector out, match the wire colors together, then crimp the lines. Finally, using a heat source, heat the heat shrink connectors to waterproof them.



1711755
Blower Motor Resistor Pigtail

Blower motor resistor 1712229 is a direct fit blower motor resistor replacement with two hole mounts.



1712229
Blower Motor Resistor

Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure, or distribution is prohibited. Global Parts Distributors, LLC (gpd) accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)