

# 2001–2002 Chevrolet Silverado/GMC Sierra 8.1 V8 Gas Engine Radiator Quick Connect Fittings: 2537C

gpd



2537C; Radiator w/ Transmission Oil Cooler  
(5 Speed Automatic Transmission)

gpd radiator, 2537C, for the 2001–2002 Chevy Silverado/Sierra 8.1 V8 Pickup will come equipped with 21 mm quick connect fittings. In the case that your transmission/engine cooler lines are not compatible with these fittings, gpd includes a set of 4 alternative 22.3 mm quick connect fittings with washers. Depending on the size of your cooler lines, you may need to replace the original quick connect fittings on the 2537C radiator.

## How to Replace Original Quick Connect Fittings on gpd Radiator 2537C

### TOOLS NEEDED

1 ¼ in. Wrench

Safety First! Always Use Eye Protection

Using a wrench, screw out the original fittings *one at a time*. If more than one fitting is taken out at a time, the cooler will fall down into the tank. Be sure to torque the newly replaced fittings to 29 ft/lbs.



- 21 mm fittings are installed at factory
- 22.3 mm fittings are included as alternatives

#106

gpdtechtips.com

Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure, or distribution is prohibited. Global Parts Distributors, LLC (gpd) accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)