

# Saturn SC/SL/SW/LS/LW Series

## Compressor: 6512025



Global Parts Distributors, LLC

TECH TIP



The 1999–2002 Saturn SW/SL/SC/LS/LW models listed below feature a compressor with an internal thermostatic control valve. When charging the system thru the low side, the thermostatic control valve will freeze open and will not allow the compressor to pump, which may lead the installer to believe that the compressor has failed.

- 2000–2001 Saturn LS
- 2000–2002 Saturn LW
- 1999–2002 Saturn SL/SC
- 1999–2001 Saturn SW



6512025

To charge the system properly for these Saturn applications, refrigerant must be pumped in on the HIGH side using a charging machine with the engine off.

#19

gpdtechtips.com

Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure, or distribution is prohibited. Global Parts Distributors, LLC (gpd) accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)