


# Service Items

## Cap & Valve Kits

Covering over 4,500 applications!

53% of cooling performance issues are related to low refrigerant, leading cause due to a leak from the service port.\*





\*2016 Mobile Air Conditioning Society (MACS) Study

### Cap and Valve Kits

Part	Description
1311422	Import/GM
1311423	GM
1311567	Chrysler/Ford/GM/Import
1311568	GM
1311569	Ford/GM
1311570	Ford/Import
1311571	Ford/Import
1311572	Chrysler/Import
1311573	Import
1311574	Import
1311575	Ford/GM/Import
1311683	Import
1311684	Import
1321363	Chrysler

## O-Ring Rapid Seal Kits

All seals needed by application.



## Temperature Testing Tool

Take the guess work out of A/C repair.



5811585

### Features:

- Digital display
- Detailed temperature and diagnostic chart
- Reads ° F and ° C

### Identify:

- Internal restrictions on condenser
- Poor air flow across the condenser

### Verify:

- Evaporator flooding levels on orifice tube system
- Expansion valve performance
- Drier refrigerant flow

## Other Popular Service Items

Visit [gpdtechtips.com](http://gpdtechtips.com) for product information and instructions.



5811423  
GM/Chrysler Denso Style Compressor Switch Puller



5811267  
R134a Valve Core Remover



5811289  
GM/Ford Orifice Tube Installer/Remover