


2009–2014 Ford F–150 Blower Motor Resistor

Options: 1712040, 1712398, and 1712678

Sometimes vehicle components are updated in the process of introducing a new model. gpd offers three blower motor resistor options for the 2009–2014 Ford F–150 models listed below. These blower motor resistor options have different internal electronics and do not interchange.

How to identify which blower motor resistor option is correct?

- Determine if the vehicle has manual or automatic climate control (Refer to gpd Tech Tip #112 for a depiction of manual vs. automatic climate controls).
- Look under the passenger’s side of the vehicle where the blower motor is located, pointing downward toward the floor.
- The blower motor resistor will be located beside the blower motor, towards the kick panel.
- Remove the blower motor connector and look at the color of the blower motor resistor housing.



1712040; Manual A/C

Ford F–150 Applications:

- 2009–2010 4.6 V8, 5.4 V8
- 2010–2014 6.2 V8
- 2011–2014 3.7 V6, 5.0 V8
- 2011–2013 3.5 V6



1712398;
Automatic A/C; Black

Ford F–150 Applications:

- 2009–2010 5.4 V8, 4.6 V8
- 2010 6.2 V8



1712678; Automatic
A/C; White

Ford F–150 Applications:

- 2009–2010 5.4 V8
- 2009–2011 4.6 V8
- 2010–2014 6.2 V8
- 2011–2014 3.5 V8
- 2011–2014 3.7 V6